

Illustrated Parts List - IPL Update



Product Name(s)

T540XP II

Description of change

The Firmware in Ignition module 587 30 68-03 has been changed to improve start behaviour.

Comments

This change is fully exchangeable.

Introduced from

| Serial number / Date | Remark |
|-----------------------------|------------------------|
| S/n 20184100193 | Valid for 587 30 68-03 |
| | |
| | |

IPL updates

| Page Title | Ref. no | New part no | Name | Excl. part no. | Remark |
|-------------------|----------------|--------------------|-----------------|-----------------------|---------------|
| Ignition system | 1 | 587 30 68-03 | Ignition module | 587 30 68-02 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |