

Illustrated Parts List - IPL Update



Product Name(s)

H T540 XP

Description of change

1. Front Handle: Material change: PP changed to PA to achieve higher impact strength.
2. Piston Assy: New part with improved margins against leakage.
3. Loop Rope Assy: Improved welding of steel wire 580 85 99-02
4. Cover: Geometrical change to improve saw dust issue.
5. Cable added to adapt to electrical (battery) chainsaw

Comments

4. Clutch cover Assy 5055431-02 (ref. 4) and Cover 5055433-02 (ref. 15) is already changed in IPL. Remark below shows info regarding s/n.
5. Diagnostic Tool Kit: Change in spare part only (no s/n)

Introduced from

Serial number / Date	Remark
20134400001	Front handle 5064952-03
20134300961	Piston assy 5852065-02
20134200193	Loop rope Assy 5808600-02
20133200001	Clutch cover Assy 5055431-02

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Handle	1	506 49 52-03	Front Handle	506 49 52-02	Is interchangeable but 5064952-02 should not be used (should be scrapped) when 5064952-03 is available
Cylinder & Piston	2	585 20 65-02	Piston Assy	505 40 39-04	5054039-04 and 5852065-02 is interchangeable
Fuel tank	11	580 86 00-02	Loop rope Assy	580 86 00-01	Is interchangeable but 5808600-01 should not be used (should be scrapped) when 5808600-02 is available
Accessories	11	583 89 71-01	Diagnostic Tool Kit	576 69 23-01	Use up and replace

Illustrated Parts List - IPL Update

