Illustrated Parts List - IPL Update



Product Name(s)

288XP/XPG

Description of change

Removal of Plug 503 27 90-04.

Reason: The plug does not fill any function anymore.

Comments


Introduced from

| Serial number / Date | Remark | | |
|----------------------|--|--|--|
| 2006-01-01 | The part has not been used in production since 2006. | | |
| | | | |
| | | | |

IPL updates

| Page Title | Ref. No | New part no | Name | Excl. part no. | Remark |
|------------|------------|-------------|------|----------------|----------------------|
| Crankcase | 6 | | PLUG | 503 27 90-04 | Remain as spare part |

1. Crankcase



Remove plug 503 27 90-04 (pos. 6).