

# Illustrated Parts List - IPL Update



Product Name(s)

**535LK**

Description of change

O-ring was removed from variants using Cover 544 11 97-01 /-02 because of assembly problems. There are no space for O-ring to be compressed.

Comments

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2020-03	

IPL updates

<b>Page title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Clutch	3		O-ring	740 42 06-00	<b>REMOVED</b>