

# Illustrated Parts List - IPL Update



Product Name(s)

**T540XPii**

Description of change

1. New Cylinder cover assy 516 03 46-03 has been introduced. The holes in Cylinder cover assy has been improved to prevent rotation of the thread insert.  
  
A new repairing Thread insert 582 52 60-01 has been introduced. See Workshop Manual.  
  
For Cylinder cover assy 516 03 46-03 use only repair Thread insert 582 52 60-01.  
  
For old Cylinder cover assy; 516 03 46-01/516 03 46-02, use repairing Thread insert 578 12 03-01.  
Repairing Thread insert 582 52 60-01 can be used on old Cylinder covers: Pre drill a  $\varnothing$  7,8 mm hole in the old Cylinder cover before adding the new thread insert 582 52 60-01.
2. New Tank cap assy and gasket number due to change of supplier.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20170400097	Valid for new Cylinder cover 516 03 46-03.
s/n 20164200289	Valid for Tank cap assy. and gasket.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder cover	1	516 03 46-03	Cylinder cover, assy	516 03 46-02	
Fuel tank	17	577 87 86-03	Tank cap assy	577 87 86-01	
	19	589 24 13-01	Gasket	505 41 10-01	
Crankcase	10	577 87 86-03	Tank cap, assy	577 87 86-01	
	12	589 24 13-01	Gasket	505 41 10-01	