

# Illustrated Parts List - IPL Update



Product Name(s)

**565**

Description of change

New reinforced Clutch cover  
Reason: Improved durability of Clutch cover.

New Knee joint kit with new brake spring(L=90)  
Reason: It was wrong brake spring (L=78) in the old kit.

Comments

New articles CLUTCH COVER ASSY 575 23 59-08 and CLUTCH COVER 575 23 63-04 are fully interchangeable.

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
20192000001	CLUTCH COVER ASSY 575 23 59-08
20192000001	CLUTCH COVER 575 23 63-04

IPL updates

<b>Page Title</b>	<b>Ref. No</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
CLUTCH COVER	1	575 23 59-08	CLUTCH COVER ASSY	575 23 59-04	New spare part
	2	575 23 63-04	CLUTCH COVER	575 23 63-02	New spare part
CHAIN BRAKE	4	590 10 56-02	KNEE JOINT KIT	590 10 56-01	New spare part