

Illustrated Parts List - IPL Update



Product Name(s)

H545

Description of change

1. Carburettor, kit: 587 08 48-02 was 587 08 48-01.
Carburettor, kit 587 08 48-02: Carburettor 588 63 53-01 (AT-7A) was 585 44 49-01 (AT-7).
Carburettor 588 63 53-01 AT-7A, which is same as 585 44 49-01 AT-7, but with changed assembly processes to improve the function.
2. Ignition Module 581 72 37-01 was 579 20 79-01. Module updated.
3. New screw (torx) for Ignition Module, easier assembly in production. 525 88 74-01 was 503 21 38-13.

Comments

Carburettor, Screw and Ignition Module: Fully interchangeable.

Introduced from

Serial number / Date	Remark
S/n 20151500385	Carburettor, kit 587 08 48-02.
2013-08-21	Ignition Module 581 72 37-01.
S/n 20151000001	Screw 525 88 74-01.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Page G Carburettor Details	10	587 08 48-02	Carburettor, kit	587 08 48-01	
Page L Ignition System	1	581 72 37-01	Ignition Module, assy	579 20 79-01	
Page L Ignition System	14	525 88 74-01	Screw	503 21 28-13	Remain as spare part.
Page N Carburettor Details	1	587 08 48-02	Carburettor, kit	587 08 48-01	