

Illustrated Parts List - IPL Update



Product Name(s)

536LiHD60X

Description of change

Battery diagnostic tool replaced with common service tool. Change of cutting deck, bottom plate assy, motor gearbox assy and connecting rod assy. Wiring assy and grease tube added.

Comments

--

Introduced from

Serial number / Date	Remark

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
A1	1	580 71 83-04	Cutting deck	580 71 83-01	
A2					New slide – For US cutting deck
B	2	577 83 45-02	Bottom plate assy	577 83 45-01	
B	8	581 51 48-02	Motor Gearbox assy	581 51 48-01	
B	9	577 82 93-02	Connecting rod assy	577 82 93-01	
D	24		Warning decal EU	581 66 30-01	
E	7	588 17 64-01	Grease tube		
E	8	579 70 93-01	Wiring assy		
F	4		Diagnostic tool	581 19 23-01	