

Illustrated Parts List - IPL Update



Product Name(s)

H135

Description of change

The functionality of the ignition module is improved. (MBU-49)

Comments

Fully interchangeable.

Introduced from

Serial number / Date	Remark
20152000002	New Ignition module 576 70 56-02 added. North America.
20153400385	New Ignition module 576 70 56-02 added.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system	7	576 70 56-02	Ignition module	576 70 56-01	