

Illustrated Parts List - IPL Update



Product Name(s)

535LST

Description of change

O-ring was removed from variants using Cover 544 11 97-01 /-02 because of assembly problems. There are no space for O-ring to be compressed.

Comments

Introduced from

Serial number / Date	Remark
2020-03	

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Clutch	3		O-ring	740 42 06-00	REMOVED