Illustrated Parts List - IPL Update



Product Name(s)	Group
136LiC	
Description of change	
IPL updates	
Comments	
Parts has been replaced by Spare Part Kit	
Grease added link to SB	

Introduced from

Serial number / Date	Remark		

IPL updates

Page Title	Ref.	New part no	Name	Excl. part no.	Remark
D	2	582 70 14-01	Housing	577 00 76 02	New Spare Part Kit
D	7		Housing	577 01 30-01	Removed, new kit pos 2
E	10	588 17 64-01	Grease		New part no, SB-B1500023