

Illustrated Parts List - IPL Update



Product Name(s)

H353

Description of change

1. We have introduced a New product variant of H353 with 3/8" cutting equipment for the Latin American market.

Comments

This update is fully exchangeable. Chain catcher 596 97 04-01 **must** be used for 3/8".

Introduced from

Serial number / Date	Remark
s/n 20205200367	Valid for New product variant.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Crankcase	24	596 97 04-01	Chain catcher	503 88 63-01	Remains as spare part
Clutch & Oil pump	3	503 98 00-03	Clutch drum 3/8"	-	New spare part.
	4	504 52 30-02	Rim 3/8"	-	New spare part.