

Product Name(s)

545 Mark II / 545G Mark II

Description of change

New improved variant of Torsion spring 582 64 49-02 to fit new driver and starter pulley

Comments

Torsion spring 582 64 49-02 is fully exchangeable.

Starter pulley is not exchangeable therefore decision was made to offer a new starter pulley kit to improve the durability, and remove Starter pulley 582 50 32-02 and Driver 582 50 31-02 as single parts.

Introduced from

Serial number / Date	Remark
2202000087	

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Starter	3		Starter Pulley	582 50 32-02	
Starter	7	596 23 05-02	Starter Assy	596 23 05-01	
Starter	14		Driver	582 50 31-02	
Starter	15	599 28 92-02	Starter Pulley	599 28 92-01	
Starter	13	582 64 49-02	Torsion Spring	582 64 49-01	