

Illustrated Parts List - IPL Update



Product Name(s)

522iHD60, 522iHD75, 522iHDR60

Description of change

Updated Housing with an extra screw introduced to provide reinforced rear handle attachment in the housing. New spare part kit 547799501 is initiated for hedge trimmer with old Housing 598369801 and 598369901. Serial number breakpoint (see below detail).

Comments

New HOUSING left and right halves are **NOT** compatible with the old left and right HOUSING part numbers.

Introduced from

Serial number / Date	Remark
Up to serial number 20241815762	New kit 547 79 95-01 if customer needs to change old HOUSING left or right. NOTE! After replacing with the new kit 547 79 95-01 for the first time, customer will be able to order both new halves 598 36 98-03 and 598 36 99-03 individually.
From serial number 20241815763	New HOUSING 598 36 98-03 and 598 36 99-03.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
HOUSING	17	547 79 95-01	HOUSING ASSY spare part kit	598 36 98-01	Up to serial number 20241815762.
HOUSING	17	547 79 95-01	HOUSING ASSY spare part kit	598 36 99-01	Up to serial number 20241815762.
HOUSING	1	598 36 98-03	HOUSING Left		From serial number 20241815763.
HOUSING	2	598 36 99-03	HOUSING Right		From serial number 20241815763.