

Illustrated Parts List - IPL Update



Product Name(s)

530iPT5, 536LiPT5

Description of change

Switch to new Tube assy with increased thickness of lower tube. This change demands new Wiring assy with new Stopper and Spacer in lower end.

Comments

Not backwards compatible.

Introduced from

Serial number / Date	Remark
Up to S/N 20244500227	Can use up old part numbers ONLY if the other old parts have not been replaced by the new ones yet. Old and new parts are not compatible, customers must control the number they receive and proceed as below.
From S/N 20244500228	Must ONLY use the new parts.

IPL updates

Page Title	Ref. no	New part	Name	Old part	Remark
Shaft	13	522 59 70-03	CLAMPING SLEEVE	522 59 70-01	Backward compatible
Shaft	14	586 91 43-02	TUBE	586 91 43-01	Complete system. Customers should only order the new parts after the tube is changed to 586 91 43-02.
Shaft	9	546 16 97-01	TUBE	587 20 73-01	Up to S/N 20244500227, not backwards compatible. If new part is received, also switch wiring assy (7) and add SPACER (21).
Electrical	7	598 76 90-01	WIRING ASSY	587 02 83-01	Up to S/N 20244500227, not backwards compatible. If new part is received, also switch tube (9) and add SPACER (21).
Shaft	21	597 79 81-01	SPACER	-	New Part. This works ONLY with new tube (9) and new wiring assy (7)
Shaft	6		SPACER,	586 87 30-01	2 pcs for TUBE 586 91 43-01 and 1 pc for new TUBE 586 91 43-02.