

# Illustrated Parts List - IPL Update



Product Name(s)

**H455E Rancher II**

Description of change

Decompression valve changed for easier startability.

Comments

Fully interchangeable

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
20142200769	New number for decompression valve.

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Cylinder piston	1	5852363-01	Decompression valve	5373105-01	<b>455E Rancher II</b>