

Illustrated Parts List - IPL Update



Product Name(s)

535FBX

Description of change

Plug, valve and hub cap will not be sold separately, but delivered as an assy, Cap assy.
Because of this update, Cutting head assy was changed from -02 to -03.

Comments

Backward compatible

Introduced from

Serial number / Date	Remark
2019-12	

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Saw head	9	N/A	Hub cap	537 22 75-01	Removed
Saw head	11	N/A	Plug	503 98 13-01	Removed
Saw head	10	N/A	Valve	537 04 03-01	Removed
Saw head	9	593 62 04-01	Cap assy		New assembly. Including valve, plug and hub cap.
Saw head	53	575 12 25-03	Cutting head assy	575 12 25-02	