

# Illustrated Parts List - IPL Update



Product Name(s)

536LiR

Description of change

IPL updates

Comments

Parts has been replaced by Spare Part Kit

Introduced from

Serial number / Date	Remark

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
D	2	582 70 14-01	Housing	577 00 76 02	New Spare Part Kit
D	7		Housing	577 01 30-01	Removed, new kit pos 2
E1	9		Grease		Updated Remark with SB-B1500023
E1	7	582 78 31-01	Motor Assy	577 02 21-03	New Spare Part Kit
E2	8		Grease		Updated Remark with SB-B1500023
E2	6	582 78 31-01	Motor Assy	577 02 21-03	New Spare Part Kit