Illustrated Parts List - IPL Update



Product Name(s)

Trouble Nume(S)	Group
122LD	_
Description of change	
Increased spark duration time. Better runability and reduced time for the warm-up of engine.	
Comments	
FULLY INTERCHANGEABLE	

Introduced from

Serial number / Date	Remark		
2019-11	Ignition module 585 07 41-02		

IPL updates

Page title	Ref no	New part no	Name	Excl. part no.	Remark
IGNITION SYSTEM	1	585074102	Ignition module	585074101	