

Illustrated Parts List - IPL Update



Product Name(s)

H450

Description of change

We have improved our ignition modules regarding sparks. (MBU-16)

Comments

Fully interchangeable.

Introduced from

| Serial number / Date | Remark |
|----------------------|--|
| 20151900001 | New Ignition module 573 93 57-02 added. North America. |
| 20152600001 | New Ignition module 573 93 57-02 added. |
| | |

IPL updates

| Page Title | Ref. no | New part no | Name | Excl. part no. | Remark |
|-----------------|---------|--------------|-----------------|----------------|--------|
| Ignition system | 7 | 573 93 57-02 | Ignition module | 573 93 57-01 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |