

Illustrated Parts List - IPL Update



Product Name(s)

325iLK

Description of change

New Motor assy due to changed Air conductor. That change makes the Holder unnecessary.

Comments

Introduced from

Serial number / Date	Remark
20224500001	New motor assy 595 01 07-08. No holder 594 02 71-01 needed on 325iLK digital variant from the stated s/n.

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
ELECTRICAL	2	595 01 07-08	MOTOR ASSY	595010703	For s/n "up to 214800120" also replace HOUSING Left to 591 44 46-02
HOUSING	5		HOLDER		For digital: Up to serial no 20224500001