

Illustrated Parts List - IPL Update



Product Name(s)

550iBTX, 550iBTX BT (967681101 and 967681102)

Description of change

For Product Numbers 967681101/ 967681102, since old motor is not produced anymore, new motor kit 547 30 65-01 is needed if customers want to replace old Motor assy 597 11 03-02.

Comments

New KIT 547 30 65-01 has to include motor and control unit because the new motor is not compatible with old control unit and old motor is not compatible with new control unit. After changing to new KIT 547 30 65-01, customers will be able to order both new components individually: FAN 529 62 63-01 and CONTROL UNIT 597 62 76-03.

Introduced from

Serial number / Date	Remark
?	-

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Fan	2	547 30 65-01	Motor assy KIT	597 11 03-02	PNC 967681101, 967681102
Fan	5	529 62 63-01	FAN SYSTEM		Only after changing to KIT 547 30 65-01.
Fan	6	597 62 76-03	CONTROL UNIT		Only after changing to KIT 547 30 65-01.