Illustrated Parts List - IPL Update



Product Name(s)

7.704.01.714		Group
H455		
Description of change		
Improved interface between crankcase and of	oil hose.	
Comments		
This update is fully exchangeable		

Introduced from

Serial number / Date	Remark
s/n 20153300193	Valid for oil hose.
s/n 20160300001	Valid for oil hose. North America

IPL updates

Page Title	Ref.	New part no	Name	Excl. part no.	Remark
Clutch & Oil pump	15	585 51 40-01	Oil Hose	537 26 14-02	