Illustrated Parts List - IPL Update

Product Name(s)

436Li

Description of change

Comments

Introduced from

Serial number / Date	Remark

IPL updates						
Page Title	Ref. no	New part no	Name	Excl. part no.	Remark	
A Crankcase	15	503 21 74-16			Quantity 3 is changed to 1	
A Crankcase	16	577 28 66-01			Article is removed => Quantity 0	
A Crankcase	27	578 22 88-02	DECAL	578 22 88-01	Changed from CSA to UL	
D Electrical	8	577 31 58-02	MOTOR ASSY	577 31 58-01		
E Accessories					Battery and charger, with cables, removed	

